

Motor – Encoder Circuit

PIC32 PWM pins:

- OC1 – D0
- OC2 – D1
- OC3 – D2
- OC4 – D3
- OC5 – D4

